


#1 - HENDLER BUILDING
SOUTH INTERIOR ELEVATION
EAST SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023


BLUE SHADING =
AREAS OF SEVERE
DETERIORATION

MAGENTA SHADING =
EXTENT OF DEMOLITION
REQUIRED



#2 - HENDLER BUILDING
SOUTH INTERIOR ELEVATION
WEST SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023




MAGENTA SHADING =
EXTENT OF DEMOLITION
REQUIRED

BLUE SHADING =
AREAS OF SEVERE
DETERIORATION




#3 - HENDLER BUILDING
WEST INTERIOR ELEVATION
SOUTH SECTION

CENTURY
ENGINEERING, LLC.
MARCH 8, 2023



#4 - HENDLER BUILDING
WEST INTERIOR ELEVATION
CENTER SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023



#5 - HENDLER BUILDING
WEST INTERIOR ELEVATION
NORTH SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023

MAGENTA SHADING =
EXTENT OF DEMOLITION
REQUIRED

BLUE SHADING =
AREAS OF SEVERE
DETERIORATION

#6 - HENDLER BUILDING
NORTH INTERIOR ELEVATION
WEST SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023



#7 - HENDLER BUILDING
NORTH INTERIOR ELEVATION
EAST SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023


MAGENTA SHADING =
EXTENT OF DEMOLITION
REQUIRED

The image shows an aerial view of the Hender Building during demolition. The building's structure is partially obscured by a dense network of steel support beams. The roof and upper walls are highlighted in magenta, indicating areas where demolition is required. Blue shading is applied to the roofline and certain wall sections, signifying severe deterioration. The surrounding area includes debris and other structures in various stages of demolition.

BLUE SHADING =
AREAS OF SEVERE
DETERIORATION

#8 - HENDLER BUILDING
NORTH EXTERIOR ELEVATION
EAST SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023



#9 - HENDLER BUILDING
NORTH EXTERIOR ELEVATION
WEST SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023


An aerial photograph of a multi-story brick building undergoing demolition. The building's exterior is highlighted with a blue semi-transparent overlay. A magenta semi-transparent overlay follows the top edge of the building, indicating the extent of demolition required. The surrounding area shows construction equipment and debris.

MAGENTA SHADING =
EXTENT OF DEMOLITION
REQUIRED

BLUE SHADING =
AREAS OF SEVERE
DETERIORATION

#10 - HENDLER BUILDING
WEST EXTERIOR ELEVATION
NORTH SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023



#11 - HENDLER BUILDING
WEST EXTERIOR ELEVATION
CENTER SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023

#12 - HENDLER BUILDING
WEST EXTERIOR ELEVATION
SOUTH SECTION

CENTURY
ENGINEERING, LLC
MARCH 9, 2023



MAGENTA SHADING =
EXTENT OF DEMOLITION
REQUIRED

BLUE SHADING =
AREAS OF SEVERE
DETERIORATION


#13 - HENDLER BUILDING
SOUTH EXTERIOR ELEVATION
WEST SECTION

CENTURY
ENGINEERING, LLC
MARCH 9, 2023



#14 - HENDLER BUILDING
SOUTH EXTERIOR ELEVATION
CENTER SECTION

CENTURY
ENGINEERING, LLC
MARCH 9, 2023



#15 - HENDLER BUILDING
SOUTH EXTERIOR ELEVATION
EAST SECTION

CENTURY
ENGINEERING, LLC.
MARCH 9, 2023